

MBRAUN Incorporated Spare Parts Price List

Maintenance of your glovebox is required for continued trouble free operation. Please see our recommended maintenance schedule at the bottom of this price list for suggested maintenance items and intervals. A limited number of spare parts can also be purchased through our online e-store at <http://shop.mbraunusa.com>. Thank you.

\$150 Minimum order required for all spare parts orders

Inertgas Purification System “Purifier” Material



Description	Part	Quantity	Cost	Image
Copper Catalyst (MB10) Kilograms	2600839	1.84 kg	\$188.42	
Molecular Sieve (MB10) Kilograms	3240262	2.75 kg	\$75.00	
Copper Catalyst (UNIlab/20G) Kilograms	2600839	4.5 kg	\$460.80	
Molecular Sieve (UNIlab/20G) Kilograms	3240262	5.5 kg	\$150.00	


Copper Catalyst (200G) Kilograms	2600839	9 kg	\$921.60	
Molecular Sieve (200G) Kilograms	3240262	11 kg	\$300.00	
Copper Catalyst (300G) Kilograms	2600839	11 kg	\$1126.40	
Molecular Sieve (300G) Kilograms	324262	17 kg	\$468.69	
Activated Carbon (internal requires 1.25 kg)	2182000	1.25 kg	\$37.50	
<p>Note: The MBRAUN Internal solvent vapor removal system should typically have the carbon changed every 1-2 months and be completely filled with carbon. The amount of carbon required will vary slightly depending on the packing of the system.</p>				
Activated Carbon (external require 5 kg)	2182000	5 kg	\$150.00	
<p>External solvent vapor removal systems should typically have the carbon changed every 3-6 months.</p>				

Glovebox Filters



Description	Part	Quantity	Cost	Image
<p>Fine Filter (MB-BF-L-03)</p> <p>MBRAUN recommends filter changes annually. Certain applications require changes more frequently, such as high particulate applications.</p>	9004513	1	\$80.00	
<p>Mann Filter</p> <p>Used for internal solvent vapor removal systems. Should be replaced every other activated carbon change.</p>	2800852	1	\$50.00	

Glovebox Gloves







Description	Part	Quantity	Cost	Image
8B1532,15 mil .4mm Thickness L/R 9.75 Hand Size	2800027	Per Pair	\$159.00	
8B1532,15 mil .4mm Thickness Ambi 9.75 Hand Size	2800028	Per Pair	\$159.00	
8B3032,30 mil .8mm Thickness L/R 9.75 Hand Size	2800031	Per Pair	\$159.00	
8B3032,30 mil .8mm Thickness Ambi 9.75 Hand Size	2800029	Per Pair	\$159.00	

*Please call MBRAUN Service for additional glove options.

Glovebox O-Rings




Description	Part	Quantity	Cost	Image
Large Antechamber O-Ring 8mm Thickness (LABmaster systems built before 1999)	OR-01	1	\$85.00	
LABmaster 4" Antechamber O-Ring	OR-02	1	\$14.00	
Glove O-Ring (2 Per Glove)	2600239	1	\$10.00	
UNIlab/LABmaster Large Antechamber O-Ring. 6mm Thickness, (Systems built after 1999)	2400309	1	\$20.00	
UNIlab 4" Mini Antechamber O-Ring	OR-18	1	\$8.50	
6" Mini Antechamber O-Ring	2400306	1	\$9.00	

6" Mini Antechamber flat gasket (Systems built after 2010 with hinged door design)	7077297	1	\$9.00	
KF-40 Centering Ring	2800018	1	\$10.00	
KF-25 Centering Ring	2800021	1	\$8.00	
KF-16 Centering Ring	2800022	1	\$6.50	

Analyzers



Description	Part	Quantity	Cost	Image
MB-OX-SE1 Solid State Analyzer	1600702	1	\$4,275.00	
MB-MO-SE1 Solid State Moisture Analyzer	1600701	1	\$3,555.00	
MB-OX-EC-PLC Electro Chemical Cell Oxygen Analyzer	1600761	1	\$5,000.00	

Miscellaneous Items



Description	Part	Quantity	Cost	Image
Regeneration Gas Flowmeter	3240052	1	\$95.00	
Regeneration Check Valve	2299000	1	\$90.00	
Internal Gloveport Cover	1600512	1	\$385.00	
External Gloveport Cover	1600513	1	\$385.00	
Internal Solvent Vapor Removal	1600325	1	\$595.00	
GSR Valve	4600977	1	\$150.00	
GSR Valve Rebuild Kit (No coil or base)	2600793	1	\$76.00	

Burkert Valve 24V DC	3210048		\$260.00	
Valve Butterfly DN40KF	9004501	1	\$375.00	
MB-BL-08 Blower for LABstar	7090527	1	\$1250.00	
MB-BL-01 Blower (UNIlab, LABmaster, MB20G, MB200G)	1600661	1	\$1600.00	
RV12 Vacuum Pump	8005233	1	Please Call MBRAUN	
XDS Vacuum Pump	2600499	1	Please Call MBRAUN	
3/8" Gas/Vacuum Feedthrough KF-40 Cap	FT-69		\$300.00	
BNC Feedthrough	FT-41	1	\$250.00	

Feedthrough Electrical 115V/15A	1600442	1	\$250.00	
6" Mini Door, Black Knob Turn Handle Style	9002012	1	\$225.00	
4" Mini Door, Red Latch Style Turn Handle UNIlab	AC-20A	1	\$340.00	
Glove port	7070842	1	\$495.00	
Glove Port Tightening Tool- For installation of glove ports and/or windows	8016003	1	\$320.00	
KF-40 Blank Cap	7002425	1	\$22.00	
KF-25 Blank Cap	7010982	1	\$8.00	
KF-16 Blank Cap	2800023	1	\$12.00	
KF-40 Clamp	3200055	1	\$11.00	

KF-25 Clamp	3200054	1	\$11.00	
KF-16 Clamp	3200053	1	\$11.00	
KF40 Electro-pneumatic valve w/electrical connection on *SAME* side as KF40 Port	9002531-K-SV	1	\$550.00	
KF40 Electro-pneumatic valve w/electrical connection on *OPPOSITE* side as KF40 Port	9002531-K-SH	1	\$550.00	
KF40 Electro-pneumatic valve w/electrical connection 90° clockwise from KF40 port	9002531-K-SL		\$550.00	
KF40 Electro-pneumatic valve w/electrical connection 90° counter- clockwise from KF40 port	9002531-K-SR		\$550.00	

MBRAUN makes every effort to keep an up to date price list for its customers. All spare parts prices listed are subject to change without notice. In addition, MBRAUN offers a large number of spare parts and accessories not listed above. Please contact MBRAUN at spareparts@mbraunusa.com or 603-773-9333 ext. 460 for a complete list of parts required for your specific system. A limited number of spare parts can also be purchased through our online e-store at <http://shop.mbraunusa.com>.

 *turning ideas into solutions*

